



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 9, 2012

Reviewed: *LAH*

Mine Name: Windy Ridge	Permit Number: S/053/0071
Operator Name: Color Country Rock	Inspection Date: May 1, 2012
Inspector(s): Lynn Kunzler, DOGM and Russell Schreiner, BM	Time: 1:30 pm
Other Participants: None	Mine Status: active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine Inspection

Inspection Summary:

This surety for this site needs to be replaced. The operator was given until May 14, 2012 to provide a replacement surety. The site showed evidence of recent activity. Russell Schreiner surveyed the quarry area with a GPS and found about 1.6 acres of disturbance. It is estimated that the access road (which will require reclamation) is just over 2 acres. This site was permitted for 5 acres of total disturbance. Trash was not a problem at this site.

Photos were taken to document site conditions

Conclusions and Recommendations:

The operator needs to provide the replacement surety by May 14, 2012. Continue to monitor this site when in the area.

Inspector's Signature

cc: Jeff Fawcett, Operator (fawcett_jeff@hotmail.com)
Russell Schreiner, BLM (rschrein@blm.gov)

O:\M053-Washington\S0530071-Windy\Inspections\insp-05012012.doc